

Plan review and installation inspection fees

Plan review performed by authorized agent (refer to link below): https://datcp.wi.gov/Pages/Programs_Services/PetroleumHazardousStorageTanksOwnerOperatorResources.aspx	Local program operator will charge a fee that must be at least equal to the state fee minus the groundwater fee.			
Any one or more tanks within the system being reviewed having a capacity of 5,000 gallons or larger	The following fees must be submitted with the plan review application for all aboveground tank systems within the scope of this program letter and ATCP 93.100, plus the groundwater fee.			
Tank System Category	Plan Review	Installation Inspection Fee	Plan Revision Fee	Tank System Category
Aggregate capacity 5,000 gallons through 48,000 gallons capacity	\$125	\$250	\$100	\$100

ATCP 93.1605(2) GROUNDWATER FEE. Pursuant to s. 168.23 (5), Stats., in addition to any fee charged by the department by rule for plan review and approval for the construction of a new or additional installation or change in operation of a previously approved installation for the storage, handling or use of flammable, combustible or hazardous liquids, the department shall collect a **groundwater fee of \$100** for each plan review submittal. The moneys collected under this subsection shall be credited to the environmental fund for environmental management.

Note #1: The groundwater fee is collected on all plans reviewed by DATCP and the City of Milwaukee.

Note #2: In accordance with s. 168.23 (5) (b), Stats., an installation that has a capacity of less than 1,000 gallons is not subject to the groundwater fee.

(3) REINSPECTION FEES. The contractor shall pay the reinspection fee to the authorized agent for any of the following reasons that require the authorized agent to make a return trip, or to reschedule a trip because the authorized agent has not been notified at least 24 hours in advance:

- (a) Failure to have the tank system accessible for inspection on the date and time specified for inspection.
- (b) Installation inspection points that are incomplete on the date and time specified for inspection.
- (c) Failure to correct deficiencies by the date and time specified for inspection.

Note: Charge and payment of reinspection fee must be supported by invoice from the respective designated inspecting agency.

ATCP 93.1605(1m) LATE FEES. The plan examination fees specified in this chapter shall be doubled for projects where the installation, erection or construction was initiated without the required departmental approval.